

SAN ANTONIO
CONVENTION CENTER
SECTION L1B

DIRECTIONS:

BEFORE APPLICATION,
USE THE WINDEX TO REMOVE
ANY OILY RESIDUE ON METAL.
THIS WILL INSURE ADHERENCE.
MIX COLD WATER AND EIGHT
DROPS OF DISH SOAP IN A SPRAY
BOTTLE AND SHAKE SOLUTION
WELL. NEXT, SPRAY METAL AND
GRAPHIC WITH A LIBERAL
AMOUNT OF SOLUTION BEFORE
APPLYING GRAPHIC TO THE
METAL. LINE UP AND LEVEL OUT
GRAPHIC ON METAL. USE
SQUEEGEE TO REMOVE
SOLUTION FROM INBETWEEN
GRAPHIC AND METAL. WIPE THE
GRAPHIC CLEAN OF SOLUTION
RESIDUE BEFORE MOVING TO
NEXT JOB.

!!!IMPORTANT!:
THE INSIDE STEEL IS
NOT AVAILABLE FOR
BRANDING.

**GRAPHIC
DIMENSIONS:**
42'L x 69"W

LABOR:

MEN= 4
TIME= 4HR

TOOLS:

SQUEEGEE
DISH SOAP
SPRAY BOTTLE
WATER
PAPER TOWELS
WINDEX

MATERIAL:

CONTROLTAC

SUGGESTIONS:

PRINT GRAPHIC IN
FOUR PIECES.

69"

42'2 1/8"

L1-EG106

FREEMAN PLANTOUR