


SAN ANTONIO  
CONVENTION CENTER  
SECTION L3C



**DIRECTIONS:**

MIX COLD WATER AND EIGHT DROPS OF DISH SOAP IN A SPRAY BOTTLE AND SHAKE SOLUTION WELL. IF NEEDED, CLEAN SURFACE OF GLASS WITH WINDEX AND TOWEL FIRST. NEXT, SPRAY GLASS AND GRAPHIC WITH A LIBERAL AMOUNT OF SOLUTION BEFORE APPLYING GRAPHIC TO THE GLASS. LINE UP AND LEVEL OUT GRAPHIC ON GLASS. USE SQUEEGEE TO REMOVE SOLUTION FROM INBETWEEN GRAPHIC AND GLASS. WIPE THE GRAPHIC CLEAN OF SOLUTION RESIDUE BEFORE MOVING TO NEXT JOB.

**GLASS / GRAPHIC  
DIMENSIONS:**

A,E(1,2)= 56"W x 56"H  
B-D(1,2)= 57<sup>1/2</sup>"W x 56"H

**LABOR:**

MEN= 2  
TIME= 3HR

**MATERIAL:**

TRU-CLING  
CLEAR CLING

**EQUIPMENT:**

1- SCISSOR LIFT  
1- 8' LADDER

**NOTE:** ALL

MUNTINS ARE  
2" WIDE

**TOOLS:**

SQUEEGEE  
DISH SOAP  
SPRAY BOTTLE  
WATER  
PAPER TOWELS  
WINDEX

L3-WC314

FREEMAN PLANTOUR