

DIRECTIONS:

MIX COLD WATER AND EIGHT DROPS OF DISH SOAP IN A SPRAY BOTTLE AND SHAKE SOLUTION WELL. IF NEEDED, CLEAN SURFACE OF GLASS WITH WINDEX AND TOWEL FIRST. NEXT, SPRAY GLASS AND GRAPHIC WITH A LIBERAL AMOUNT OF SOLUTION BEFORE APPLYING GRAPHIC TO THE GLASS. LINE UP AND LEVEL OUT GRAPHIC ON GLASS. USE SQUEEGEE TO REMOVE SOLUTION FROM INBETWEEN GRAPHIC AND GLASS. WIPE THE GRAPHIC CLEAN OF SOLUTION RESIDUE BEFORE MOVING TO NEXT JOB.

SAN ANTONIO
CONVENTION CENTER
SECTION L3B


GLASS

DIMENSIONS:

A= 55"W x 38^{1/4}"H
B= 55^{1/8}"W x 38^{1/4}"H

GRAPHIC
DIMENSIONS:

110^{7/8}"L x 38^{1/4}"W



MEETING ROOMS 220-225
HALLS 1-4
BRIDGE HALL

LABOR:

MEN= 2
TIME=1HR

TOOLS:

SQUEEGEE
DISH SOAP
SPRAY BOTTLE
WATER
PAPER TOWELS
WINDEX

SUGGESTIONS:

PRINT GRAPHIC IN
ONE SOLID PIECE

MATERIAL:

TRU-CLING
CLEAR CLING