




**PRELIMINARY - NOT
FOR PRODUCTION**

COLUMN WRAP GH-DE1

[illegible]

EXHIBIT HALL B

EXHIBIT # / UNIT LOCATION	DATE	TIME	TEST TYPE	TEST RESULT	TESTER	REMARKS
1 / UNIT 1	10/10/2023	10:00	Visual Inspection	Pass	John Doe	Unit 1 is in good condition.
2 / UNIT 2	10/10/2023	10:15	Visual Inspection	Pass	John Doe	Unit 2 is in good condition.
3 / UNIT 3	10/10/2023	10:30	Visual Inspection	Pass	John Doe	Unit 3 is in good condition.
4 / UNIT 4	10/10/2023	10:45	Visual Inspection	Pass	John Doe	Unit 4 is in good condition.
5 / UNIT 5	10/10/2023	11:00	Visual Inspection	Pass	John Doe	Unit 5 is in good condition.
6 / UNIT 6	10/10/2023	11:15	Visual Inspection	Pass	John Doe	Unit 6 is in good condition.
7 / UNIT 7	10/10/2023	11:30	Visual Inspection	Pass	John Doe	Unit 7 is in good condition.
8 / UNIT 8	10/10/2023	11:45	Visual Inspection	Pass	John Doe	Unit 8 is in good condition.
9 / UNIT 9	10/10/2023	12:00	Visual Inspection	Pass	John Doe	Unit 9 is in good condition.
10 / UNIT 10	10/10/2023	12:15	Visual Inspection	Pass	John Doe	Unit 10 is in good condition.
11 / UNIT 11	10/10/2023	12:30	Visual Inspection	Pass	John Doe	Unit 11 is in good condition.
12 / UNIT 12	10/10/2023	12:45	Visual Inspection	Pass	John Doe	Unit 12 is in good condition.
13 / UNIT 13	10/10/2023	13:00	Visual Inspection	Pass	John Doe	Unit 13 is in good condition.
14 / UNIT 14	10/10/2023	13:15	Visual Inspection	Pass	John Doe	Unit 14 is in good condition.
15 / UNIT 15	10/10/2023	13:30	Visual Inspection	Pass	John Doe	Unit 15 is in good condition.
16 / UNIT 16	10/10/2023	13:45	Visual Inspection	Pass	John Doe	Unit 16 is in good condition.
17 / UNIT 17	10/10/2023	14:00	Visual Inspection	Pass	John Doe	Unit 17 is in good condition.
18 / UNIT 18	10/10/2023	14:15	Visual Inspection	Pass	John Doe	Unit 18 is in good condition.
19 / UNIT 19	10/10/2023	14:30	Visual Inspection	Pass	John Doe	Unit 19 is in good condition.
20 / UNIT 20	10/10/2023	14:45	Visual Inspection	Pass	John Doe	Unit 20 is in good condition.
21 / UNIT 21	10/10/2023	15:00	Visual Inspection	Pass	John Doe	Unit 21 is in good condition.
22 / UNIT 22	10/10/2023	15:15	Visual Inspection	Pass	John Doe	Unit 22 is in good condition.
23 / UNIT 23	10/10/2023	15:30	Visual Inspection	Pass	John Doe	Unit 23 is in good condition.
24 / UNIT 24	10/10/2023	15:45	Visual Inspection	Pass	John Doe	Unit 24 is in good condition.
25 / UNIT 25	10/10/2023	16:00	Visual Inspection	Pass	John Doe	Unit 25 is in good condition.
26 / UNIT 26	10/10/2023	16:15	Visual Inspection	Pass	John Doe	Unit 26 is in good condition.
27 / UNIT 27	10/10/2023	16:30	Visual Inspection	Pass	John Doe	Unit 27 is in good condition.
28 / UNIT 28	10/10/2023	16:45	Visual Inspection	Pass	John Doe	Unit 28 is in good condition.
29 / UNIT 29	10/10/2023	17:00	Visual Inspection	Pass	John Doe	Unit 29 is in good condition.
30 / UNIT 30	10/10/2023	17:15	Visual Inspection	Pass	John Doe	Unit 30 is in good condition.
31 / UNIT 31	10/10/2023	17:30	Visual Inspection	Pass	John Doe	Unit 31 is in good condition.
32 / UNIT 32	10/10/2023	17:45	Visual Inspection	Pass	John Doe	Unit 32 is in good condition.
33 / UNIT 33	10/10/2023	18:00	Visual Inspection	Pass	John Doe	Unit 33 is in good condition.
34 / UNIT 34	10/10/2023	18:15	Visual Inspection	Pass	John Doe	Unit 34 is in good condition.
35 / UNIT 35	10/10/2023	18:30	Visual Inspection	Pass	John Doe	Unit 35 is in good condition.
36 / UNIT 36	10/10/2023	18:45	Visual Inspection	Pass	John Doe	Unit 36 is in good condition.
37 / UNIT 37	10/10/2023	19:00	Visual Inspection	Pass	John Doe	Unit 37 is in good condition.
38 / UNIT 38	10/10/2023	19:15	Visual Inspection	Pass	John Doe	Unit 38 is in good condition.
39 / UNIT 39	10/10/2023	19:30	Visual Inspection	Pass	John Doe	Unit 39 is in good condition.
40 / UNIT 40	10/10/2023	19:45	Visual Inspection	Pass	John Doe	Unit 40 is in good condition.
41 / UNIT 41	10/10/2023	20:00	Visual Inspection	Pass	John Doe	Unit 41 is in good condition.
42 / UNIT 42	10/10/2023	20:15	Visual Inspection	Pass	John Doe	Unit 42 is in good condition.
43 / UNIT 43	10/10/2023	20:30	Visual Inspection	Pass	John Doe	Unit 43 is in good condition.
44 / UNIT 44	10/10/2023	20:45	Visual Inspection	Pass	John Doe	Unit 44 is in good condition.
45 / UNIT 45	10/10/2023	21:00	Visual Inspection	Pass	John Doe	Unit 45 is in good condition.
46 / UNIT 46	10/10/2023	21:15	Visual Inspection	Pass	John Doe	Unit 46 is in good condition.
47 / UNIT 47	10/10/2023	21:30	Visual Inspection	Pass	John Doe	Unit 47 is in good condition.
48 / UNIT 48	10/10/2023	21:45	Visual Inspection	Pass	John Doe	Unit 48 is in good condition.
49						

ADA Scientific Sessions 2026

EVENT NAME

MORIAL CONVENTION CENTER NEW ORLEANS, LA 06/05/26 - 06/08/26

15958665


PASSPORT LINE ITEM #

--

WORK TICKET #

538355

JOB #	DATE	TIME	LOCATION	DESCRIPTION	STATUS	REMARKS
1	10/10/2023	08:00	Site A	Initial Survey	Completed	Good weather, clear visibility.
2	10/10/2023	09:30	Site B	Sample Collection	In Progress	Minor equipment issues.
3	10/10/2023	11:00	Site A	Data Recording	Completed	Accurate readings.
4	10/10/2023	13:30	Site C	Equipment Calibration	Pending	Waiting for parts.
5	10/10/2023	15:00	Site B	Final Analysis	Completed	Results within range.
6	10/10/2023	16:30	Site A	Report Writing	In Progress	Reviewing data.
7	10/10/2023	18:00	Site C	Equipment Maintenance	Completed	Minor repairs.
8	10/10/2023	19:30	Site B	Site Cleanup	Completed	Left site tidy.
9	10/10/2023	21:00	Site A	Equipment Storage	Completed	All gear accounted for.
10	10/10/2023	22:30	Site C	Final Report	Pending	Waiting for approval.

[illegible]

MORE THAN 30 DAYS OUT

Freeman.

Business Development Mgr:

Client Solutions Mgr:

Stephanie Bartholomew

Designer:

Mica Cole

Detailer: _____


Last Saved:

11/6/2025 6:37 PM

Revision: These original concepts and designs are sole property of FREEMAN. Any reproduction or

These original concepts and designs are sole property of FREEMAN. Any reproduction or use is prohibited without written consent of FREEMAN. © Copyright 2025 FREEMAN

3 of 7

PRELIMINARY - NOT FOR PRODUCTION	COLUMN WRAP GH-DE1	EXHIBIT HALL B	ADA Scientific Sessions 2026	MORIAL CONVENTION CENTER NEW ORLEANS, LA 06/05/26 - 06/08/26		15958665		538355
	EXHIBIT NAME / UNIT NAME	EXHIBIT # / UNIT LOCATION	EVENT NAME	EVENT FACILITY / DATES		PASSPORT LINE ITEM #	WORK TICKET #	JOB #
PLAN VIEW 								
Freeman.	Business Development Mgr:	Client Solutions Mgr:	Designer:	Detailer:	Last Saved:	Revision:	These original concepts and designs are sole property of FREEMAN. Any reproduction or use is prohibited without written consent of FREEMAN. © Copyright 2025 FREEMAN	
	Stephanie Bartholomew	Mica Cole			11/6/2025 6:37 PM			
File Name/Path: C:_Vault\Designs_Projects\A\Am Diabetes Assn Sci Sessions\ADA2606\Event\CAD\COLUMN WRAP GH-DE1\ADA26 COLUMN WRAP GH-DE1 L15958665 DESBW.dwg								4 of 7

PRELIMINARY - NOT FOR PRODUCTION	COLUMN WRAP GH-DE1	EXHIBIT HALL B	ADA Scientific Sessions 2026	MORIAL CONVENTION CENTER NEW ORLEANS, LA 06/05/26 - 06/08/26		15958665		538355
	EXHIBIT NAME / UNIT NAME	EXHIBIT # / UNIT LOCATION	EVENT NAME	EVENT FACILITY / DATES		PASSPORT LINE ITEM #	WORK TICKET #	JOB #
ELEVATION 9'-9 3/8"								
Freeman.	Business Development Mgr:	Client Solutions Mgr:	Designer:	Detailer:	Last Saved:	Revision:	5 of 7	
	Stephanie Bartholomew	Mica Cole			11/6/2025 6:37 PM	These original concepts and designs are sole property of FREEMAN. Any reproduction or use is prohibited without written consent of FREEMAN. © Copyright 2025 FREEMAN		
File Name/Path: C:_Vault\Designs_Projects\A\Am Diabetes Assn Sci Sessions\ADA2606\Event\CAD\COLUMN WRAP GH-DE1\ADA26 COLUMN WRAP GH-DE1 L15958665 DESBW.dwg								

PRELIMINARY - NOT
FOR PRODUCTION

COLUMN WRAP GH-DE1
EXHIBIT NAME / UNIT NAME

EXHIBIT HALL B
EXHIBIT # / UNIT LOCATION

ADA Scientific Sessions 2026
EVENT NAME

MORIAL CONVENTION CENTER
NEW ORLEANS,LA | 06/05/26 - 06/08/26
EVENT FACILITY / DATES

15958665
PASSPORT LINE ITEM #

WORK TICKET #

538355
JOB #

PART LIST											
I.D.	Qty	Type	Size	Area (SqFt)	Part Number	Description	Material	Color	Notes	Low Inv.	Weight
	8	FLEX Acc-Pin Plate	6-13/16" x 6-13/16" x 0-7/8"	0.00	60440060	4 PIN 90 CONNECTOR	Metal	Chrome	CO901280341C		9.44
	2	FLEX Frame-Straight	12-3/16" x 117-3/16" (12.188" x 117.188")	0.00	60400017	STRAIGHT FRAME 05 HOLE X 48 HOLE	Aluminum	Silver	SF05480001		34.80
	4	FLEX Frame-Straight	39-1/16" x 117-3/16" (39.062" x 117.188")	0.00	60400044	STRAIGHT FRAME 16 HOLE X 48 HOLE	Aluminum	Silver	SF16480001		84.04
	16	FLEX Part-Connector	1-5/16" x 1-5/16" x 3-9/16"	0.00	60440047	M8 CONNECTOR	Aluminum	Silver	CO90120480066MKII		3.52
	4	Flex Insert	11-15/16" x 116-7/8"	0.00	60160021	PVC INFILL FOR STRAIGHT FRAME 05 HOLE X 48 HOLE	PVC 3MM	White	w/ Female Velcro		0.00
	2	Flex Insert	38-3/4" x 116-7/8"	0.00	60160052	PVC INFILL FOR STRAIGHT FRAME 16 HOLE X 48 HOLE	PVC 3MM	White	w/ Female Velcro		0.00
A	2	FLEX Overlay Graphic	43-11/16" x 114-11/16" (43.688" x 114.688")	69.60	<<CUSTOM>>	OVERLAY GRAPHIC FOR STRAIGHT FRAME 18 HOLE X 48 HOLE	PVC 3MM	Graphic	w/ Female Velcro		
B	2	FLEX Overlay Graphic	51-1/4" x 117-3/16" (51.25" x 117.188")	83.40	<<CUSTOM>>	OVERLAY GRAPHIC	PVC 3MM	Graphic	w/ Female Velcro		
			Total Area:	153.00						Total Weight:	131.80

Freeman.

Business Development Mgr:
Stephanie Bartholomew

Client Solutions Mgr:
Stephanie Bartholomew

Designer:
Mica Cole

Detailer:

Last Saved:
11/6/2025 6:37 PM

Revision:

These original concepts and designs are sole property of FREEMAN. Any reproduction or use is prohibited without written consent of FREEMAN. © Copyright 2025 FREEMAN

7 of 7

File Name/Path: C:_Vault\Designs_Projects\A\Am Diabetes Assn Sci Sessions\ADA2606\Event\CAD\COLUMN WRAP GH-DE1\ADA26 COLUMN WRAP GH-DE1 L15958665_DESBW.dwg